



# CARRIER

Draft Inducer Replacements  
by Rotom

## FB-RFB756

- 115 Volts • P.S.C
- 1.02 AMP • OPEN ENCL.
- 1/16 HP • BALL BEARING
- 3190 RPM

**PACKARD:** 66756, **A.O. SMITH:** JE1D013N,  
**CARRIER:** 320725-756, 320725756,  
HC28CQ116, HC27CB115, **ICP:** 1179081,  
**EMERSON:** K33HXCW-1017, **GRAINGER:**  
34VH22, **JOHNSTONE SUPPLY** X83-386

## FB-RFB757

- 115 Volts • P.S.C
- 1.16 AMP • OPEN ENCL.
- 1/16 HP • BALL BEARING
- 3026 RPM

**PACKARD:** 66757, **A.O. SMITH:** JE1D010N,  
**CARRIER:** 320725-757, 320725757,  
325270-761, 320725-754, HC27CB119,  
HC27CB116, **GRAINGER:** 40LW03,  
**JOHNSTONE SUPPLY** X83-387

## FB-RFB758

- 115 Volts • P.S.C
- 1.45 AMP • OPEN ENCL.
- 1/15 HP • BALL BEARING
- 3222 RPM

**PACKARD:** 66758, **A.O. SMITH:** JE1D014N,  
**CARRIER:** 320725-758, 320725758, 317292-753,  
320725-755, 325269-701, 325270-761,  
320725755, 325269701, 320725758, HC28CQ115,  
**BROADOCEAN:** YDZ-050L22541-01,  
**GRAINGER:** 115U77, **JOHNSTONE SUPPLY**  
X83-388